

IN THE UNITED STATES PATENT & TRADEMARK OFFICE

ATTORNEY DOCKET NUMBER: 200300032-2

IN RE APPLICATION OF: U.S. Patent No. 7,623,482

USPTO CONFIRMATION CODE: 7891

APPLICATION NO.: 10/625,291

FILED: Jul. 23, 2003

EXAMINER: SAI MING CHAN

GROUP ART UNIT: 2416

FOR: SYSTEM AND METHOD FOR EFFECTUATING THE TRANSFER OF DATA BLOCKS INCLUDING A HEADER BLOCK ACROSS A CLOCK BOUNDARY

37 CFR 1.322 & 37 CFR 1.323 REQUEST FOR CERTIFICATE OF CORRECTION

HONORABLE COMMISSIONER OF PATENTS & TRADEMARKS

Sir:

The following is a request for a certificate of correction in Serial Number 10/625,291, now Patent Number 7,623,482.

A certificate of correction under 35 USC 254 is respectfully requested in the above-identified patent.

All errors were the fault of the USPTO, no fee required. In the event that a further fee is required, please charge the amount to Deposit Account No. 082025.

All errors were the fault of the applicant and, accordingly, please charge \$100.00 to our Deposit Account No. 082025. In the event that a further fee is required, please charge the amount to the same Deposit Account.

The errors were the fault of both the applicant and USPTO and, accordingly, please charge \$100.00 to our Deposit Account No. 082025. In the event that a further fee is required, please charge the amount to the same Deposit Account.

The exact location where the error appears in the patent and patent application is as follows:

In column 11, line 13, in Claim 12, delete "N" and insert -- M --, therefor.  
(Amendments to claims filed on Feb. 27, 2009, page 9, in claim 12, line 5)

The requested correction is attached on Form PTO 1050.

Respectfully Submitted

4/15/2010  
DATE

  
Name: Steven L. Webb  
Registration No.: 44, 395

Attorney/Agent of Record

HEWLETT-PACKARD COMPANY  
Intellectual Property Administration  
3404 E. Harmony Road  
Mail Stop 35  
Fort Collins, CO 80528

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

Page 1 of 1

PATENT NO. : 7,623,482

APPLICATION NO. : 10/625,291

ISSUE DATE : Nov. 24, 2009

INVENTOR(S) : Richard W. Adkisson et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 11, line 13, in Claim 12, delete "N" and insert - - M - -, therefor.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Hewlett-Packard Company  
Intellectual Property Administration  
3404 E. Harmony Road  
Mail Stop 35  
Fort Collins, CO 80528

This collection of information is required by 37 CFR 1.322, and 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patent, P.O. Box 1450, Alexandria, VA 22313-1450.